



*Please enter information in the empty box next to each section	Water System Name	BETHALTO, IL	System ID Number:	IL1190150	Current Inventory Date:	5/2/2025	
---	-------------------	--------------	-------------------	-----------	-------------------------	----------	--

Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)	Copper - No Lead Solder (C)							
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)	Copper - Lead Solder (CLS)							
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)	Galvanized (G)							
		Lead (L)					Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)	Galvanized Requiring Replacemnt (GRR)							
		Cast/Ductile Iron or Transite (O)					Lead (L)	Lead (L)		Cast/Ductile Iron or Transite (O)							
		Plastic - PVC, HDPE, PEX (P)					Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)		Cast/Ductile Iron or Transite (O)							
		Unknown (U)					Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)		Plastic - PVC, HDPE, PEX (P)							
Unknown Not Lead (UNL)	Unknown (U)	Unknown (U)		Unknown (U)													
							Unknown Not Lead (UNL)	Unknown Not Lead (UNL)									
870 1ST AVE		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
880 1ST AVE		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
511 2ND ST		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
515 2ND ST		N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	COPPER	COPPER	COPPER	N	N/R	N			N		
523 2ND ST		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
603 2ND ST		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
611 2ND ST		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
618 2ND ST		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
619 2ND ST		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
620 2ND ST		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
622 2ND ST		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
624 2ND ST		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
628 2ND ST		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
632 2ND ST		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
636 2ND ST		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
640 2ND ST		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
704 2ND ST		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
729 2ND ST		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
733 2ND ST		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
737 2ND ST		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
743 2ND ST		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
745 2ND ST		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
747 2ND ST		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
751 2ND ST		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
754 2ND ST		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
755 2ND ST		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
758 2ND ST		N</															

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

4682 CULP LN		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
4688 CULP LN		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
4700 CULP LN		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
4711 CULP LN		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
4737 CULP LN		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
4761 CULP LN		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
4778 CULP LN		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
4779 CULP LN		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
4785 CULP LN		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
4801 CULP LN		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
4820 CULP LN	LA1A097	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
4835 CULP LN		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
4845 CULP LN		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
7318 CULP MEADOWS LN		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
7335 CULP MEADOWS LN		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
7336 CULP MEADOWS LN		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
7354 CULP MEADOWS LN		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
7371 CULP MEADOWS LN		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
7372 CULP MEADOWS LN		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
7388 CULP MEADOWS LN		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
1 CYPRESS ST		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
2 CYPRESS ST		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
3 CYPRESS ST		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
4 CYPRESS ST		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
5 CYPRESS ST		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
6 CYPRESS ST		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
7 CYPRESS ST		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
9 CYPRESS ST		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
10 DELAWARE		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
13 DELAWARE		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
14 DELAWARE		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
18 DELAWARE		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
5 DELAWARE CT		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
116 DALEWOOD DR		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
130 DALEWOOD DR		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
138 DALEWOOD DR		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
406 DAVID ST		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
407 DAVID ST		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
408 DAVID ST		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
411 DAVID ST		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
414 DAVID ST		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
415 DAVID ST		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
419 DAVID ST		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
1 DELL AVE		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
7 DELL AVE		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
14 DELL AVE		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
15 DELL AVE		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
25 DELL AVE		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
26 DELL AVE		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
33 DELL AVE		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
34 DELL AVE		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
38 DELL AVE		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
39 DELL AVE		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
42 DELL AVE		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
55 DELL AVE		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
56 DELL AVE		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
67 DELL AVE		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
68 DELL AVE		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
87 DELL AVE		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
88 DELL AVE		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
93 DELL AVE		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
1 DOGWOOD CT		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
2 DOGWOOD CT		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
3 DOGWOOD CT		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
4 DOGWOOD CT		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
5 DOGWOOD CT		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
6 DOGWOOD CT		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
7 DOGWOOD CT		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
8 DOGWOOD CT		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
105 DOROTHY ST		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
205 DOROTHY ST		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

196 S MORELAND RD		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
200 S MORELAND RD		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
201 S MORELAND RD		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
401 S MORELAND RD		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
480 S MORELAND RD		N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	COPPER	L	L	N	N/R	N			N		
482 S MORELAND RD		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	L	L	N	N/R	N			N		
596 S MORELAND RD		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	L	L	N	N/R	N			N		
711 S MORELAND RD		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
650 S MORELAND RD		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
705 S MORELAND RD		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
750 S MORELAND RD		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
802 S MORELAND RD		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
806 S MORELAND RD		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
810 S MORELAND RD		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
814 S MORELAND RD		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
900 S MORELAND RD		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
905 S MORELAND RD		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
1005 S MORELAND RD		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
1025 S MORELAND RD		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
1045 S MORELAND RD		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
720 W MORO DR		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
710 W MORO RD		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
401 NEBRASKA ST		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
601 NEBRASKA ST	LA1A092	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
606 NEBRASKA ST		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
610 NEBRASKA ST		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
700 NEBRASKA ST		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
701 NEBRASKA ST		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
704 NEBRASKA ST		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
705 NEBRASKA ST		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
708 NEBRASKA ST		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
709 NEBRASKA ST		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
712 NEBRASKA ST		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
713 NEBRASKA ST		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
717 NEBRASKA ST		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
15 NELSON DR		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
16 NELSON DR		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
18 NELSON DR		N															

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

37 W WOODLAND DR		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
38 W WOODLAND DR		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
39 W WOODLAND DR		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
41 W WOODLAND DR		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
46 W WOODLAND DR		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
52 W WOODLAND DR		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
58 W WOODLAND DR		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
66 W WOODLAND DR		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
67 W WOODLAND DR		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
71 W WOODLAND DR		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
79 W WOODLAND DR		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
85 W WOODLAND DR		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
86 W WOODLAND DR		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
91 W WOODLAND DR		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
92 W WOODLAND DR		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
98 W WOODLAND DR		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
1 WOODS LN		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
2 WOODS LN		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
3 WOODS LN		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
4 WOODS LN		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
5 WOODS LN		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
WRESTLING CENTER		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
200 WRIGLEY FIELD DR		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
201 WRIGLEY FIELD DR		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
202 WRIGLEY FIELD DR		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
203 WRIGLEY FIELD DR		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
216 WYOMING ST		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
301 WYOMING ST		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
304 WYOMING ST		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
305 WYOMING ST	LA1A096	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	COPPER	UNL	UNL	N	N/R	N			N		
309 WYOMING ST		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
404 WYOMING ST		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
405 WYOMING ST		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
408 WYOMING ST		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
409 WYOMING ST		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
412 WYOMING ST		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
412 WYOMING ST		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
413 WYOMING ST		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
416 WYOMING ST		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
417 WYOMING ST		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
420 WYOMING ST		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
421 WYOMING ST		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
424 WYOMING ST		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
425 WYOMING ST		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
428 WYOMING ST		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
429 WYOMING ST		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
432 WYOMING ST		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
433 WYOMING ST		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
436 WYOMING ST		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
437 WYOMING ST		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
440 WYOMING ST		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
441 WYOMING ST		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
444 WYOMING ST		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
500 WYOMING ST		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
501 WYOMING ST		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
504 WYOMING ST		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
505 WYOMING ST		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
508 WYOMING ST		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
509 WYOMING ST		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
513 WYOMING ST		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		
602 WYOMING ST		N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	COPPER	UNL	UNL	N	N/R	N			N		